

# Quality Assurance Labs Inc.

NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES

80 PLEASANT AVENUE • SOUTH PORTLAND, MAINE 04106 • TEL: (207) 799-8911 • FAX: (207) 799-7251

## INSPECTION REPORT

CUSTOMER: S. W. COLE ENGINEERING			PAGE 1 OF 1	
ADDRESS: GRAY, ME.				
ATTENTION: ROGER DOMINGO				
COPIES: FILE				
PROJECT: T. D. BANK - 1410 CONGRESS ST., PORTLAND, ME.				
OWNER: SAME				
CONTRACTOR: PIZZAGALLI CONSTRUCTION				
JOB No.: 08-0395.2	REPORT No.: QAL-10-2232	P. O. NUMBER:	DATES INSPECTED: 12 - 08 - 10	

### REMARKS

>>>>>> SITE VISIT TO PERFORM VISUAL INSPECTIONS OF STRUCTURAL STEEL FIELD CONNECTIONS PER SITE DOCUMENTS AND AWS D1.1, D1.3 REQUIREMENTS: GRID LOCATIONS 1 - 4, A1 - D FOR ALL ROOF FRAMING PLANS.


- > COLUMN ANCHOR BOLTED AND WELDED CONNECTIONS COMPLETE.
- > COLUMN TO BEAM AND BEAM TO BEAM HIGH STRENGTH BOLTED CONNECTIONS COMPLETE.
- > HSS DIAGONAL WELDED BRACE CONNECTIONS COMPLETE. TO INCLUDE ANGLE BRACE KICKERS.
- > BAR JOIST AND BRIDGING CONNECTIONS COMPLETE.
- > ROOF DECKING ATTACHMENTS FOR PUDDLE WELDS AND SIDE LAP SCREWS COMPLETE.
- > TOWER FRAMING PLAN AT C - D, 3.4 - 4 SHOWS ALL HIGH STRENGTH BOLTED COLUMN TO BEAM AND ROOF RAFTER BEAM CONNECTIONS COMPLETE. ROOF DECKING ATTACHMENTS COMPLETE.

COMPLETED ITEMS COMPLY WITH SITE DRAWINGS AND AWS D1.1, D1.3 REQUIREMENTS FOR VISUAL ACCEPTANCE.

END ITEMS ////

**FAA REPAIR STATION NUMBER RX5R187N**  
METHOD(S),PROCESS(ES),PROCEDURE(S) MERCURY FREE

ADDITIONAL INFORMATION - SEE ATTACHED:  SKETCH(ES)  SUPPLEMENTARY SHEET(S)  NDT REPORTS  VIDEO

<b>SIGNATURES</b>			<b>CERTIFICATION</b>		<b>DATE</b>			
			LEVEL	M	D	Y		
INSPECTOR	M. Drew	CWI # 99050211		ASNT	II	12	08	10
SUPERVISOR								