

**LETTER OF TRANSMITTAL**

Project #: 07133  
Date: 3/23/11


Project: TD Bank, Westgate Plaza, 1410 Congress Street  
To: Pizzagali Construction  
131 Presumpscot Street  
Portland, Maine 04103

Attention: Mark Donovan

Regarding: Permit Drawings

THESE ARE TRANSMITTED AS CHECKED BELOW:

- Attached       Under separate cover via
- Shop Drawings     Prints/Plans       Specifications       Samples
- Copy of letter       Change Order       Diskettes           Other: \_\_\_\_\_

COPIES	DATE	NO.	DESCRIPTION
1	3-23-11		Stamped Structural Report
			

THESE ARE TRANSMITTED AS CHECKED BELOW:

- For approval       Approved as submitted       Resubmit \_\_\_\_\_ copies for approval
- For your use       Approved as noted       Submit \_\_\_\_\_ copies for distribution
- As requested       Returned for corrections       Return \_\_\_\_\_ corrected prints
- For review and comment       Other: \_\_\_\_\_
- FOR BIDS DUE ON: \_\_\_\_\_       PRINTS RETURNED AFTER LOAN TO US

**REMARKS**

Mark-

Included is the Stamped Structural Report for Nick Adams

Adam

COPIES TO: (File)      SIGNED: \_\_\_\_\_

If enclosures are not as noted, kindly notify us at once.  
\\P:\2007\07133\05-TRANSLot\_Tocity\_2008-0912.Doc

Adam J. Redbord

**CONSTRUCTION FIELD  
OBSERVATIONS**

Project:	TD Bank 1410 Congress St. Portland, ME	Date:	12/21/2010
Date/Time Observed:	12/15/2010, 11:00 am	Project No.:	07133.00
Weather:	Partly Sunny, 20 degrees	Report No.:	No. 1
Prepared By:	Paul Livernois PE		
Distribution:	(MF17.0)		

Present at site: ED Hume, Pizzagalli Construction Co.; Paul Livernois, SMMA

**THE FOLLOWING WORK WAS OBSERVED TO BE COMPLETED OR IN PROGRESS:**

**I. Construction Status:**

1. Foundation and Steel erection for the Building has been completed.
2. The slab-on-grade has not yet been placed.
3. Exterior wall construction was in progress.

**II. Observation Activity:**

1. There was light activity on site when we arrived. The structural steel inspector from S.W.Cole was on site on 12/08/10 and performed a thorough inspection of the steel framing, joists, and deck. The report listed no issues with the completed work.
2. The metal stud sub-contractor was continuing with the erection of the exterior stud work, which was approximately 70% complete.

**III. Observation Remarks:**

1. We reviewed the foundation work and the structural steel erection and found both to be satisfactorily erected. The quality of the steel fabrication and the erection appeared to be quite satisfactory overall. We also found no apparent issues to correct or resolve.

