



REPAIR NOTATION	
DESIGNATION	SEE DWG. S201 & S202 FOR REPAIR DETAILS
1	INDICATES TYPE 1 BEAM REPAIR. SEE DWG S201.
2	INDICATES TYPE 2 GIRDER REPAIR. SEE DWG S201.
T	TRUSS REINFORCEMENT. SEE DWG S202.
P	INDICATES POST REPAIR. SEE DWG S201.
R	INDICATES BEAM TO BE REPLACED WITH NEW TO MATCH EXISTING U.N.O.
	INDICATES DECK TO BE REPLACED WITH NEW TO MATCH EXISTING.
	INDICATES WALL REPLACEMENT. SEE DWG S202.

Date: 11/26/13

Scale: 1/8" = 1'-0"

Revisions:

Project: **Brick North**
Thompson's Point Portland, ME

Architect: **ARCHETYPE architects**
48 Union Wharf Portland, Maine 04101
(207) 772-6022 Fax (207) 772-4056

Consultant: **VEITAS VEITAS engineers**
680 Granite Street, Suite 10184
TEL: (207) 843-2883 FAX: (207) 846-2005

Prepared For: **Thompson's Point Development Company Inc.**

S103

Existing Roof Framing Plan

