

Observation Report 022 Precast Concrete

Date:	10/26/2004	
Time:	10:00 AM	
Temp:	40 F	
Weather:	cloudy and cool	

_	Port	and	, ME	Ξ		_				
8	326									
/	Architectural Precast Panels Line W.1 and Y.1 from line 29 to 38 have been installed									
_										
-										
_										
		Not Completed	WA W			Satisfactory	Unsatisfactory	Not Completed	N/A	Additional Items:
L		(Erection Pro	oceaures					
)	< <		Fitup Bearing Su	faces					
F	-									
L	#									
F	+	+	+			-				
	² ane	els w	ere	being erecte	d with minima	l bea	aring	j. P	late	s were being added and modification
r	nade	e. R	epre	esentative fro	m BPDL was	on s	ite a	and	in c	ommunications with there engineer.
_	he (32 fc	ot p	anels on bot	h sides that s	pan	fror	n lin	e 29	9 to 32 have a severe bow.
<u> </u>	rec	ast b	ear	ing connection	ns was modif	ied i	n fie	eld a	t Y.	1/32. 4x6 Tube was replaced with
6	3x6 t	ube.								