

## Observation Report 025 Precast Concrete

Date: 11/1/2004

Time: 10:30 AM

Temp: 40 F

Weather: cloudy and cool

| t:  | Portland, ME   |      |      |                     |                    |              |                |               |     |                   |           |
|-----|--|------|------|---------------------|--------------------|--------------|----------------|---------------|-----|-------------------|-----------|
|     |  |      |      |                     |                    |              |                |               |     |                   |           |
|     | 826  |      |      |                     |                    |              |                |               |     |                   |           |
| on: | Architectural Precast Panels on Line W.1 from line 28 east   |      |      |                     |                    |              |                |               |     |                   |           |
|     |  |      |      |                     |                    |              |                |               |     |                   |           |
|     |  |      |      |                     |                    |              |                |               |     |                   |           |
|     |  |      |      |                     |                    |              |                |               |     |                   |           |
|     | Х  | X    | A/N  | Erection Procedures | es                 | Satisfactory | Unsatisfactory | Not Completed | N/A | Additional Items: |           |
|     | X  |      |      |                     | Plumbness<br>Fitup |              |                |               |     |                   |           |
|     | Х  |      |      |                     | Bearing Surfaces   |              |                |               |     |                   |           |
|     |  |      |      |                     |                    |              |                |               |     |                   |           |
|     |  |      |      |                     |                    | Ţ            |                |               |     |                   |           |
|     |  |      |      |                     |                    |              |                |               |     |                   |           |
|     | These panels have gone up much better than previous panels there are no apparent bearing issue or visible warps or bowing of panels. |      |      |                     |                    |              |                |               |     |                   |           |
|     |  |      |      |                     |                    |              |                |               |     |                   |           |
|     |  |      |      |                     |                    |              |                |               |     |                   |           |
|     |  |      |      |                     |                    |              |                |               |     |                   |           |
| l:  | Tod  | ld N | Л. N | leal                | , P.E.             |              |                | Dat           | e:  |                   | 11/1/2004 |