



Photo 1: Area where proposed outfall will daylight.



Photo 2: Existing Culvert to be replaced by proposed 24" SD outfall.



Photo 3: View of existing bank where outfall pipe will extend down. Note slope erosion occurring in the existing condition. New outfall will extend down and outlet at the toe of the slope with velocity reducing rip rap outlet.



Photo 4: Section of existing CMP culvert that has washed away from the rest of the culvert, highlighting the need for replacement.



Photo 5: Fore river sewer interceptor pipe CSO Structure. Access road will be constructed to left. Light clearing will be required to complete the access road.