

## Permitting and Inspections Department Michael A. Russell, MS, Director

October 26, 2017

BOUWENS DON M & 47 SAUNDERS ST PORTLAND, ME 04103

CBL: 263 C019001

Located at: 40 WEBB ST

Certified Mail 7014 1820 0001 4049 6911

Dear BOUWENS DON M &,

An evaluation of the above-referenced property on 10/25/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 9 days of the date of this notice (30 days for ceiling to be repaired if needed). A reinspection of the premises will occur on 11/03/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Jason Duval

Code Enforcement Officer

## CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager BOUWENS DON M &		Inspector Jason Duval	Inspection Date 10/25/2017
Location	CBL	Status	Inspection Type
40 WEBB ST	263 C019001	Failed	Housing Safety Inspection
Code	Int/Ext Floor	Unit No. Area	Compliance Date

1) 205

Violation:

SMOKE ALARMS / LEVEL; Smoke Alarms - One and Two-Family Dwellings: Single-station or multiplestation (interconnected) photoelectric smoke alarms must be powered by the building electrical system or powered by a 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) within 21 feet of any door to a sleeping room and (2) in living areas separated by doors on each level of the dwelling unit and (3) including the basement.

NFPA 101 (2009) 24.3.4.1(2)(3), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes:

Replace broken Smoke/CO combo for first floor common area.

2) 207

Violation:

CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes:

Replace broken Smoke/CO combo for first floor common area.

3) 211-006-108(b)

Violation:

BUILDING INTERIORS - MINIMUM STANDARDS FOR INTERIOR FLOORS, WALLS, CEILINGS AND DOORS; Every floor, wall, ceiling, and door shall be in a structurally sound condition and in good repair and shall be substantially vermin proof.

City Code of Ordinances Section 6-108(b)

Notes:

Repair kitchen ceiling.

First floor needs new Smoke/CO combo. Ceiling in kitchen needs to be repaired within 30 days. Comments: