389 Congress St.Rm 315 Portland, ME 04101 Phone: (207)874-8700 Fax: (207)874-8716

facsimile transmittal

10:	Diversified Properties	S	From:	Mike Nugent/Je	eanie Bourke
Fax:	773-6875		Date:	December 2, 200)2
Phone:	773-4988		Pages: 1		
Re:	33, 36 & 40 Barclay A	ive.			
□ Urge	ent □ For Review	☐ Please Cor	nment	☑ Please Reply	☐ Please Recycle
	•	• •		• •	•
		39 E018 & 339 E			
	I have completed the review and have the following questions/comments? 1) What is the type/size of the anchor bolts?				
		• •		olts? the spacing of the l	ally achima is
	excessive	ng girder is unde	ruesigneu	the spacing of the	ially columns is
		thing not shown-			
		-	ing of the	4060 windows in th	ne sleeping rooms.
			ows adjace	ent to the tubs is red	quired
	· · · · · · · · · · · · · · · · · · ·	ess is not shown.			1 11 1000
	7)The stairs cannot be placed in the opening shown and comply with 1999 BOCA stair requirements. Please redesign and resubmit. Als o include a cross				
	section that shows, treads, risers, nosing, headroom, width & guard details.				
	8) What is being used for exterior wall sheathing?				
	9) Please provide a fastener schedule.				
		-		the slider. (no decl	
			on of the p	perimeter drain that	t includes pipe/stone
	& fabric	-	stoir spoos	including treads, r	isors posing
		m & width.	stair specs	including treads, r	isers, nosing,
			lan the 2-2		n is underdesigned
		foot opening.	1411 1110 2 2	2 A 10 Conterecus	ii is underdesigned
	14) wnat is	the header for ex	terior wind	lows & slider.	