

Permitting and Inspections Department Michael A. Russell, MS, Director

October 17, 2017

BOAC GROUP LLC 142 HIGH ST # 215 PORTLAND, ME 04101

CBL: 429 H002001

Certified Mail 7014 1820 0001 4047 1826

Located at: 82 SHERWOOD ST

Dear Boac Group Llc,

An evaluation of the above-referenced property on 10/17/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 10 days of the date of this notice. A re-inspection of the premises will occur on 10/27/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

Pad lock brackets outside bedroom need to be removed by end of day 10/17/2017

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Jason Duval

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager			Inspector	Inspection Date
Boac Group Llc		Jason Duval	10/17/2017	
Location	CBL		Status	Inspection Type
82 SHERWOOD ST	429 H002001		Failed	Inspection
Code	Int/Ext	Floor	Unit No. Area	Compliance Date

1) 207

Violation:

CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes:

Immediately address the missing CO alarms in the upstairs bedrooms for each unit.

2) 55.300

Violation:

NFPA 101- 31.2.2.2.2.1 DOORS LOCKED AGAINST EGRESS; NO DOOR IN ANY MEANS OF

EGRESS SHALL BE LOCKED AGAINST EGRESS WHEN THE BUILDING IS OCCUPIED.

Notes:

IMMEDIATELY remove pad lock brackets from the outside of the bedroom in upstairs area in right side

unit.

Comments:

Missing Co alarm in both upstair bedroom areas. One bedroom had a outside lock that needs to be

removed by end of day 10/17/17.