

cfpt
12-18 Portland Pier

On unnamed alley in rear of the Thomas Block from Pearl St.,
(Burgess Fobes Co.) there is a very dilapidated building
at the corner of Portland Pier, with bay windows facing West,
apparently owned by George I. Lewis, with sheet iron sides. Some
of these strips have fallen down on the North side, and others
are weakening. This structure is much worse than any of
Cramson's, and is a fire and health menace in some respects.

Mr. Torrey left this

Rec'd 4/18/55

WJ

DELIVERING		<input type="checkbox"/> Deliver ONLY to address <input checked="" type="checkbox"/> Show address where delivered
EM LOYEE		
Received from the Postmaster the Registered or Insured Article, the number of which appears on the face of this return receipt.		
Sives K. Ringer (Signature or name of addressee)		
2 (Signature of addressee's agent—Agent shall enter addressee's name on it if ONL-1500) Date of delivery OCT 19 1956		
Form 654 GPO: 1956 U. S. GOVERNMENT PRINTING OFFICE: 16-1244		

Ref. Mail
Return Receipt

WHD 11/19/56

October 17, 1956

Crypt. Rear of about 12-18 Portland Pier (Assessor's Lot No. 30-B-5)

Copy to Mr. Kriger

Mr. Lewis H. Kriger
Center Realty Inc.
22 Portland Pier

Dear Mr. Kriger:

The two-story wooden frame building, used presently for storage, at the rear of about 12-18 Portland Pier (Assessor's Lot No. 30-B-5) is found to be broken, weakened and out of repair so as to be unsafe or dangerous.

As authorized by Section 109 of the Building Code of Portland (copy enclosed) you are hereby required to have these dangerous conditions permanently corrected before November 19, 1956.

From as close an examination as could be made under the circumstances, it is my belief that the remedy is to completely demolish this building. It is my impression that you have been considering removing the upper story only, providing a roof over the first story and continuing the building as a one-story building.

However, your attention is called to the fact that the condition of the exterior wall of the building toward Custom House Wharf is such as to indicate that the sub-structure of the building, probably including the wharf structure itself, is definitely defective—a condition which has no doubt contributed to the deterioration of the building.

A building permit from this department is required before demolition of any part of the building or alteration of the building is undertaken.

Very truly yours,

Warren McDonald
Inspector of Buildings

WHD/B

Enc: Copy of Section 109 of the Building Code



INDUSTRIAL ZONE
CITY OF PORTLAND, MAINE

DEPARTMENT OF BUILDING INSPECTION

COMPLAINT

INSPECTION COPY

COMPLAINT NO. 55/16

Date Received 3/9/55

Location 12-18 Portland Pier

Use of Building

Owner's name and address Mrs. Emma Jordan, c/o Mr. Joseph G. Jordan Telephone 2-2-632

Telephone

Tenant's name and address 131 Commercial St.

Telephone

Complainant's name and address Ned

Telephone

Description Dangerous condition in building

NOTES:

3-2-3-15 "Doll" type metal truck owned by Ned
was seen going to place to have some paint done.
A black "U" shaped tray was placed under the
truck. When I asked what he had in the tray he
stated "I am going to paint a man down there".
He appears to have been drunk, "that's the
last place I'd go around here." He also
said "I'm going to paint a truck
and truck enough here."

4-14-15 - One pm - See letter of 4/10/55

12-18 Portland Pier
Location

April 5, 1955

Cplt. 12-18 Portland Pier—Dangerous condition of building supports
and foundation

Mrs. Emma Jordan
c/o Mr. Joseph C. Jordan
131 Commercial St.

Dear Mrs. Jordan:

Following our letter to you of March 9 requiring correction of the defective condition of post and foundation in the first story of your building at 12-18 Portland Pier, we received your letter by Joseph assuring that steps would be made to investigate and correct the difficulty.

Later a man came to the office and tried to apply for a building permit to change out the wooden post to structural steel columns. Our permit clerk told him that we would need a plan showing both the design of the columns and the foundations of them before we could issue such a permit under the law. He said that he had no such plan and had no authority to have one made and would have to receive further instructions. He also said that the work of changing out the post was nearly completed, and then left the office. Now, Mrs. Jordan, I know that you realize that we are not trying to make things unnecessarily complicated, and that the information that we need before a permit can be issued is for the eventual benefit of the owner as well as all parties involved.

I found time to examine the situation on April 4, and found that two large wooden columns had been replaced by two structural steel H-columns with plate top and bottom. I have little doubt that the columns are strong enough to take the loads, but I do not recollect that the bearing plates at top and bottom were anchored. More important, I learned by inquiry that the fill under the concrete floor had merely been brought up to a good level, compacted and the column bearing plate and patching of the concrete floor mostly supported on this compacted fill. If you had followed the usual procedure and filed a plan we would have insisted that some type of concrete foundation be provided beneath the floor, or such a depth that the filled-in material beneath the floor, if washed out or set led by any means, as happened before, the foundation and the columns would remain well supported.

We are not disposed to raise any questions about the job now; but as far as I can see, any settlement or displacement of the material beneath the floor is likely to immediately affect the stability of the steel columns. It is important that you keep track of this condition and make sure that everything is stable before any very heavy loads are placed on the second floor.


Very truly yours,

Warren McDonald
Inspector of Buildings

WMD/B

JOSEPH F. JORDAN
AUDITOR & TREASURER

JOSEPH C. JORDAN
GENERAL MANAGER



127-137 COMMERCIAL STREET
PORTLAND 3, MAINE
TELEPHONE 2-2832

Wm. C. Jordan
March 10, 1955

March 10, 1955.

Warren McDonald
Inspector of Buildings
Portland, Maine


Dear Mr. McDonald:

This is to inform you that we are proceeding with our investigation and correction of conditions at our garage at Portland Pier as was mentioned in your letter of February 9th.

We will advise you what measures are to be taken and will ask your advice as to whether these alterations will be satisfactory.

Very truly yours,
Joseph C. Jordan
for
Mrs. Emma Jordan.

JCF/gb



"THERE IS NO SUBSTITUTE FOR JORDAN'S QUALITY"

0-12-18 Portland Pier

March 9, 1955

Registered Mail
Return Receipt

Mrs. Emma Jordan
c/o Mr. Joseph C. Jordan
131 Commercial St.

Dear Mrs. Jordan:-

An inspector from this office has found a dangerous condition in the building which you are reported to own or control at 12-18 Portland Pier.

As directed by Sect. 109a of the Building Code (copy enclosed) you are hereby required to have made before March 23rd, 1955, such changes, repairs or alterations as may be necessary to permanently correct this dangerous condition.

The second floor over this former garage and perhaps the roof also are supported by a number of heavy steel beams and at least one large wooden girder or beam, all running at right angles to the driveway of Portland Pier. In the center of this wooden girder is a large wooden post. Examination of the bottom of the post shows that it is badly rotted, and has little, if any, bearing upon the material beneath the post. Strangely enough the heavy beam overhead is not in contact with the top of the post but is about one-quarter or an inch above it, though it is evident that the bolster at the top of the post has been spiked to the girder.

It is not easy to see what happened, but it is easy to see that this girder could and did get a bearing again upon the post, thereby causing the girder to settle back into place. In this connection it is important that absolutely no further loads be put on the second floor than exist now, and that the loads there now should not be changed in location--until the condition is permanently corrected.

There is another peculiar condition which may or may not be dangerous. The concrete floor of the former garage is broken on a line at right angles with the driveway toward Commercial St. It appears to have raised and there is quite a lot of void space beneath the concrete slab. This crack comes directly at this post, and no doubt there is some association between the two defects.

We are particularly concerned about this crack and the unevenness of the floor because your present tenant is setting upon the raised part of the slab a large, but not very heavy, gas-fired furnace for drying venetian blinds. We are concerned lest he put this appliance in operation and then the slab return to its former level and possibly rupture the gas supply line, which of course would be a hazard to your building, the entire wharf and perhaps the entire water front.

We shall have to ask that you work together with this tenant to see to it that nothing like that occurs.

Very truly yours,

W.M.D./G
Enclosure: Copy of Sect. 109 of the
R.R. 1st Ave. Div.,
Inspector of Buildings

FILL IN AND SIGN WITH INK



**APPLICATION FOR PERMIT FOR
HEATING, COOKING OR POWER EQUIPMENT**

Portland, Maine, March 8, 1925.

PERMIT ISSUED
OCT 25 1953
CITY OF PORTLAND
MAR. 9 1955

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 12, Portland, Pier. Use of Building... cleaning plant., No. Stories 2, REG Building
 Name and address of owner of appliance. Wards, Venetian Blind Laundry, (A. R. Maco) 2-1/4 Existing
 Installer's name and address Portland Gas Light Co., 5 Temple St. Telephone 2-8361

General Description of Work

To install Venetian blind drying machine

...

P HEATER, OR POWER BOILER

Permit issued with Letter

Name and type of burner 1st floor Any burnable material in floor surface or beneath? no
 Will operator be always in attendance? no
 Type of floor beneath burner ...
 Location of oil storage ...
 Low water shut off ... Make ...
 Will all tanks be more than five feet from any flue? ...
 Total capacity of any existing storage tanks for furnace burners ...

IF OIL BURNER

Labelled by underwriters' laboratories? ...
 Does oil supply line feed from top or bottom of tank? ...
 Size of vent pipe ...
 Number and capacity of tanks ...
 From front of appliance ... Front sides and back ...
 Size of chimney flue ... Other connections to same flue ...
 Is hood to be provided? ... If so, how vented? ...
 If gas fired, how vented? ...
 Rated maximum demand per hour ...

IF COOKING APPLIANCE

Location of appliance ... Any burnable material in floor surface or beneath? ...
 If so, how protected? ... Distance to combustible material from top of appliance? ...
 Skirting at bottom of appliance? ... Height of legs, if any ...
 From front of appliance ... Front sides and back ...
 Size of chimney flue ... Other connections to same flue ...
 Is hood to be provided? ... If so, how vented? ...
 If gas fired, how vented? ...
 Forced or gravity?

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Made by Venetian Blind Laundry Equipment Co., Wichita, Kansas
 Vent. pipe will have 2 or 3 in. clearance under a wooden beam, shield to be provided
 Amount of fee enclosed? 2.00. (\$2.00 for one heater, etc. 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED:

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? Yes, ...

INSPECTION COPY

Signature of Installer by ...

CITY OF PORTLAND

Portland Gas Light Co.

NOTES

Permit No.	Location	Owner	Date of Permit	Approved
351283	3000' off Hwy 30	John & Gail	3/9/55	3/9/55

Decision of next commission

3-1455 "The G" Simp. Structure in Water Next Friday	3-1455 "McLain" Inland, Maryland McLain's property Kline at 100 ft. by 100 ft. deep	3-2455 "Baldwin" Rocky Point Off the Harbor Wharf Rd. 100 ft. by 100 ft. deep	3-2455 "Bell" Rocky Point Off the Harbor Wharf Rd. 100 ft. by 100 ft. deep
That there is no evidence of any of these three meets the first, second and third parts of the plan is an invalid title plan	That the first and third parts are to be rejected for lack of evidence	That the first and third parts are to be rejected for lack of evidence	That the first and third parts are to be rejected for lack of evidence
and the second part and they are rejected	and they are rejected	and they are rejected	and they are rejected
and the second part and they are rejected	and they are rejected	and they are rejected	and they are rejected
and the second part and they are rejected	and they are rejected	and they are rejected	and they are rejected

March 9, 1955

AP - 12 Portland Pier
Installation of gas-fired venetian blind drying machine.

Portland Gas Light Co.

5 Temple St.

Marcus Venetian Blind Laundry

12 Portland Pier

Gentlemen:-

Copy to owner of the building
*To the Manager
12 Portland Pier*

After talking things over with Mr. Gibson of the Gas Light Co. and with the owner of the appliance, an examination of the building, the permit for installation is issued herewith, subject to the following conditions. If those conditions are not understood, or, if you are unable or unwilling to comply with them, connection and use of the appliance should not take place, but you should contact this office with more information to secure compliance with the regulations.

1. Apparently this appliance has no draft hood incorporated in it. Section 602ab of the Building Code provides that vent connectors shall have draft hoods when required by and shall be designed and installed according to the best engineering practice, and that the vent connectors shall pitch generally upwards from the appliance to the connection with the flue without depressions or pockets to prevent free circulation. There is very little difference in level of the vent outlet of the appliance and opening to the chimney flue. We have been able to find no regulations as to whether or not the best engineering practice requires draft hoods. It is hoped that the engineers of the Gas Company will determine both of these factors from the standpoint of safe operation before connecting the gas to the appliance.

2. Somewhat contrary to the information on the application, the clearance between the top of the two vent connectors and the wood of a heavy beam, which supports the second floor, will be only about one inch. The owner of the appliance has agreed to provide Type B vent pipe where these two vents pass under this beam and extending far enough beyond the sides of the beam in each case so that no ordinary vent pipe (not Type B) will be closer than nine inches to any woodwork. In fact, he agreed to use a Type B vent from the appliance connections to a point at least nine inches beyond the beam as the connector proceeds on toward the chimney. In addition to the use of the Type B vent, the owner is to supply a shield of no less than 28 gauge metal, suspended on non-combustible spacers from the wooden beam so that there will be an air space both between the shield and wooden beam and between the shield and the top of the Type B vent. This metal shield is to extend at least nine inches beyond each side of the wooden beam.

3. There is a defective condition of the concrete floor where the appliance is to be mounted. It appears that a part of the concrete floor may have been raised by some action so that there is more or less space beneath the concrete slab on which the appliance is to be mounted. What caused this distortion or whether or not the slab will go back into place is not known; but the owner of the appliance should bear in mind that he must bear the responsibility of any distortion or rupture of gas pipes in such a case.

4. Fairly close to the appliance is a large wooden post, evidently designed to support the large wooden beam referred to above, and this wooden beam is one of the

Portland Gas Light Co. - - - - - 42
Wares Venetian Blind Laundry

March 9, 1935

Major supports of the second floor of the building. The bottom of this wooden post is badly rotted and appears to have very little, if any, bearing on the material beneath the floor. Strangely enough the large wood beam does not get direct bearing on the top of this post but sets about a quarter of an inch above the top of the post.

5. These two conditions may be dangerous. On that basis we are requiring the owner of the building to take steps to make the situation permanently safe. It would seem that the owner of the appliance, for his own interest, should understand that these changes to provide safety may mean to the appliance and to his business.

Very truly yours,

Warren McDonald
Inspector of Buildings.

WMD/G

Photograph and blueprint returned to Wares Venetian Blind Laundry