

Cctober 31, 1979 /

Hr. Robert Hill 1019 Congress Street Portland, Maine 04102

Dear Mr. Hill:

Re: 1019 Congress Street - 65-B-8 - NCP-Libbytown

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code.

Good maintenant, is the best way to protect the value of your property and neighborhood.

Please-feel free to call-on us if we can be of assistance to you.

Sincerely-yours,.
Joseph E.-Gray, Jr., Director
Neighborhood Conservation

Lyle A. es, Chief of Housing Inspections

or or Portian	a A	IK EX	No 16HI	"RHOOD CONSERVAII Theck Off Sheet		Housing [Housing Inspection Division 1) Insp. Name	
	<i>()</i>	K. F.K	J. SIRICIU	RE INSPECTION SCH		l) Insp. Na		
12) Hous No. 13	A (D)	-4)PTOColed	15) Direct lo Scree	11. 7) Lot 6 % 15th	s:Tract	11k, 10)insp 1 7 1)St. Ms	11) Form No.	
18)Cwner or Age	nt: Ko	Back -11	35	7(2,7)		19)St -tus	20) Fldg's Rat.	
21)Address:						± 60	20//102 5 1.21.	
72 Turey La. F	ete.					Zip Code		
23)D. Units 24)00	cc.D. 's 2	(5) Rr. Jn:t. 2	6) 0cc k U s _ 1) 110. c	occupants 28)Cc	1 i'. 29)81		s 3.)Const.Mat 32)0.B's	
3 <u>3)C.H. 34)Pi</u>	10. 3	5)4 medFor, 3	6)Actual Lin. Use	38)Lks.	Ac. Bth. Fac			
EXTERIOR - St			Cd. Viol	Yes Clor - Stri	NO	<u> </u>		
Foundation /alls	E. /FO		3a	11-,h:	1		Cd. Viol.	
Roof	EA/WA RO			Tiec. Wiring	- -		8 8e	
Perch	20		3a	Fluors	FL			
Stairs	'DX/SR		3 <u>d</u>	Walls	IN WA		3b	
Steps	P		<u>3d</u> 3d	Ceilings	CE		3b	
Poors	DO			Windows	1N, Wf		36	
Windows	E (/I/I		<u></u> <u></u>	Airshafts	AS	/	3e	
Eaves	EA		3a	Roof Rafters	ROR		3a	
Trim			3a	Sanitation	SAN	· .	46	
Chimney	CF.			Stairways Stair Freads	IN/SRW	, 	3d	
Gutters		7	За	Wastelines	SRT	<u> </u>	3d	
Roof Drains	ED		3 ε	Supply Lines	WSL		€d	
<u>Bulkhead</u>	BU		3d	Sracks	LUS		60	
Outbuild	GR - SI	1	46	Flues	FU	<u> </u>	3e	
Yand	YA			Vents	VE /	<u> </u>	<u>3e</u>	
Garbage	G⊁			C. Lanev	IN/Ch	 _	3,	
Rubbish	RU		41.	Heating Equip.		Consolination -	3e	
Containers	co	<u> </u>	/1	Bemt. Sanication	n linter -		SPE 9c	
Drainage	DR			Dampness	- DM	LI Debris - Di		
Infestation	IN-CR-F	L	40	Lighting			3a	
Rats Other	RA		4.4	Elec. Pare			<u>δ</u> c	
			41	Scales	BS R	,		
Pire Ascape Dual Liggesh	FE.		10	Foundatio			34	
Drivesave	DI,		16	"loor Joints	FL (10	<i></i>	. 2	

Inspection Services P. Samuel Hoffses



Planning and Urban Development Joseph E. Gray Jr.

CITY OF PORTLAND

JUNE 24, 1997

1017 CONGRESS STREET PTSHP PO BOX 10152 PORTLAND ME 04104

> Re: 1019 CONGRESS ST CBL: 065- - B-008-001-01 DU: 3

Dear Sir:

You are hereby notified, as owner or agent, that an inspection was made of the above-referenced property. Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached "Housing Inspections Report".

In accordance with the provisions of the above-mentioned Code, you are hereby ordered to correct those defects within sixty (60) days. A reinspection for code compliance will be made at the expiration date of this notice. If the violations have not been corrected, this matter will be referred to Corporation Counsel for legal action.

Please Note: You should consult this department to insure that any corrective action you should undertake complies with the building, plumbing, electrical, zoning and other Articles of the City Code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in its goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Sincerely,

David Jordan Code Enforcement Officer Tammy Munson

Code Enfc. Offr./ Field Supv.

HOUSING INSPECTION REPORT

Location: 1019 CONGRESS ST Housing Conditions Date: JUNE 24, 1997 Expiration Date: AUGUST 23, 1997

Items light below are in violation of Article V of the Municipal Codes, "Housing Codes", and must be corrected before the expiration date:

1. EXT - BASEMENT - WALLS APPEAR TO NEED TO BE REPOINTED

2. EXT - LEFT/REAR - 108
CHIMNEY APPEARS TO NEED TO BE REPAIRED

3. EXT - RIGHT -METAL FASCIA IS MISSING

4. EXT - RIGHT CORNER -SOFFIT IS OPEN 109.40

5. EXT - REAR -DEBRIS IS STORED

6. INT - OVERALL -HARD-WIRED BATTERY-BACK/UP SMOKE DETECTORS ARE REQUIRED IN EACH UNIT

389 Congress Street • Portland, Maine 04101 • (207) 874-8704 • FAX 874-8716 • TTY 874-8936

