

Inspection Services
F. Samuel Hoffses
Chief



Planning and Urban Development
Joseph E. Gray Jr.
Director

MARCH 17, 1997

CITY OF PORTLAND

ITTS TIMOTHY
84 SOUTH ST
ESSEX JTN VT 05452

Re: 57 ALLEN AVE
CBL: 435- - G-020-001-02
DU: 24

Dear Mr. Itts:

During a recent inspection of the property owned by you at the above-referred address, it was noted that smoke detectors were missing/inoperable in some locations.

25 MRSA 2464 required that approved smoke detectors be installed in each apartment in the immediate vicinity of the bedrooms. When activated, the detector shall provide an alarm suitable to warn the occupants within the individual unit. Failure to comply with this statute may result in a fine of up to \$500 for each violation.

Reinspection of your property will be made in twenty-four (24) hours. Lack of compliance will result in referral of the matter for legal action.

Loss control is a responsibility of your management. Our observations are intended to assist you. Recommendations are a result of conditions observed at the time of our visits. They do not necessarily include every possible loss potential code violation, or exception to good practice.

Please read and implement the attached formal code interpretation or determination - Number 93-1 - March 10, 1993 - from the State Fire Marshall's office.

Sincerely,

Merle Leary
Merle Leary
Code Enforcement Officer

Tammy Munson
Tammy Munson
Code Enfc. Offr./ Field Supv.