Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 02/25/15

on

st Floor

Dec 2014

		Size	Frame Data		Door Data		HW Set	Notes
	tibule	Existing to Remain						
102	Vestibule to Lobby	Existing to Remain						
103	Lobby to Bath	Existing to Remain						
104	Lobby to Bath	Existing relocated						
105	Waiting to Corridor	3070	HM 16 ga	RH	Wood: full glass	LHR	Passage	Sidelight Frame
106	Reception to Manager	3070	HM 16 ga	RH	Wood: half glass	RH	Lock	
107	Corridor to Reception Office	3070	HM 16 ga	RH	Wood: half glass	RH	Passage	
108	Corridor to Stair	3070	HM 16 ga	LH ULB	HM: narrow light	RHR	Lockset	
109	Corridor to Dr Office	3070	HM 16 ga	LH	Wood: Full glass	LH	Lockset	
110	Corridor to Operatory	3070	HM 16 ga	RH	Wood: TBD	LHR	Passage	Door pending salvage
111	Corridor to Operatory	3070	HM 16 ga	LH	Wood: TBD	RHR	Passage	Door pending salvage
112	Corridor to Operatory	3070	HM 16 ga	RH	Wood: TBD	LHR	Passage	Door pending salvage
113	Corridor to Operatory	3070	HM 16 ga	RH	Wood: TBD	LHR	Passage	Door pending salvage
115a	Corridor to Stair	3070	HM 16 ga	LH ULB	HM: narrow light	RHR	Lock	
114	Corridor to Operatory	3070	HM 16 ga	RH	Wood: TBD	LHR	Passage	Door pending salvage
116	Corridor to Operatory	3070	HM 16 ga	RH	Wood: TBD	LHR	Passage	Door pending salvage
117	Corridor to Break Room	3070	HM 16 ga	LH	Wood: Full glass	RHR	Passage	
118	Changing Room	Existing to Remain						
119	Changing Room	Existing to Remain						
120	Boy Scout Shop Entry	Existing to Remain						
121	Break Room to Stair	3070	HM 16 ga	LH ULB	HM: narrow light	RHR	Lock	
122	Locker Room to Bath	3070	HM 16 ga	RH	Wood: flush	RH	Privacy	
123	Closet	3070	HM 16 ga	LH	Wood: flush	RHR	Passage	
124	Storage	3070	HM 16 ga	RH	Wood: flush	RH	TBD	Lock TBD
125	Lobby to Recovery	3070	HM 16 ga	LH ULB	HM: Flush	LH	Lock	PG21 Alarm?
126	Single Recovery	3070	HM 16 ga	LH	Wood: TBD	RHR	Passage	Door pending salvage
127	Elevator Lobby to Waiting	3070	HM 16 ga	LH	Wood: full glass	RHR	Lock	Sidelight frame