Inspections Division
Date: 06/06/17

there are no vents on Heat pumps