Inspections Division
Date: 07/23/15

Second Floor - Proposed Changes

Notes:

Replacement Windows (Same Location and Size as Existing Windows