Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 02/09/16

39 Exchange Street. We will be replacing two existing Heat Pumps, replacing them with one. This is the location of the existing heat pumps

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 02/09/16

We will leave the existing electrical conduit in place, and replace the two refrigerant lines with one set of refrigerant lines. Similar design will be employed using black insulation

The Heat Pumps themselves are located behind a fence. Where there were two heat pumps, there will be one