ANSUL

Hyatt Place

Install Date: 1/

By:
Cintas Fire Prot
443 Fore Stree
Portland, ME 0
603-717-7300

Reviewed for Code Compliance
Inspections Division
Approved with Conditions

Date: 02/11/14

Hyatt Place
Hyatt Place




## Flow Summary:

| Coverage | Dim. | Nozzle | Flows | Notes |
|---|---|---|---|---|
| Hood: Single Bank | 184 x 54 | 1N x2 | 2 | 2-4 in. from filter face,center of height dimension, aimed down filter length. |
| Duct: Square | 14 x 10 | 1100 | 1 | 2-8 in. into center of duct opening, aimed up |
| Duct: Square | 14 x 10 | 1100 | 1 | 2-8 in. into center of duct opening, aimed up |
| Fryer: 1 vat, dripboard | 16 x 26 | 3N | 3 | 25"–35", FRONT HALF of perimeter, aimed at center |
| Range: 2 burners | 12 x 26 | 1F | 1 | 40"–48", front edge of burner, nozzle flats parallel with burner front-to-rear cente ... See Note 1 |
| Griddle | 36 x 26 | 1N | 1 | 35"–40", 0-2 in. inside perimeter, aimed at center |
| Pizza Oven | 36 x 36 | 1N x2 | 2 | Opposite ends (either corner) of the enclosed cooking chamber, 1 to 3 inches above s ... See Note 2 |
| Total Flow Points | | | 11 | |