Reviewed for Code Compliance
Inspections Division
Approved as Noted
Date: 08/11/17

The Sign will be secured with standard steel sign bracket attach at the top and side of sign along with (2) 45 degree wind braces secured to the building