Reviewed for Code Compliance
Inspections Division
Approved with Conditions

Date: 05/13/16

© Copyright 2016 Osc

10 PRECAST DOUBLE TEE EDGE AT RETAINING WALL
1/2" = 1'-0"

9 PRECAST DOUBLE TEE BEARING AT RETAINING WALL
1/2" = 1'-0"

8 PRECAST DOUBLE TEE EDGE AT RETAINING WALL
1/2" = 1'-0"

7 PRECAST DOUBLE TEE EDGE AT FIRE WALL
1/2" = 1'-0"

6 PIER BETWEEN O.H. DOORS AT FUTURE FIRE WALL
1/2" = 1'-0"

5 DOOR OPENINGS AT FUTURE FIRE WALL OPENING
1/2" = 1'-0"

4 PRECAST DOUBLE TEE BEARING AT WINDOW OPENINGS
1/2" = 1'-0"

3 PRECAST DOUBLE TEE BEARING AT RETAINING WALL
1/2" = 1'-0"

2 PRECAST DOUBLE TEE BEARING AT RETAINING WALL
1/2" = 1'-0"

NOTE:
IF SPACE AND EXCAVATION ALLOWS REVERSE TOE AND HEEL OF FOOTING TO MATCH TYPICAL WALL SECTIONS.

KEY ONLY REQUIRED AT NORTH EAST CORNER OF WALL TO PAST THE CORNER OF EXISTING BUILDING ON ADJACENT LOT.

1 PRECAST DOUBLE TEE BEARING AT RETAINING WALL
1/2" = 1'-0"

BECKER
STRUCTURAL ENGINEERS
75 York Street, Portland, Maine 04101
207.879.1838 ■ beckerstructural.com

OPECHEE
CONSTRUCTION CORPORATION
11 CORPORATE DRIVE ■ BIBLEPORT ■ NH 03220
PHONE (603) 527-6006 ■ WWW.OPECHEECO.COM

STATE OF MAINE
TODD M. NEAL
NO. 9406
LICENSED
PROFESSIONAL ENGINEER

Mixed Use Development

York & High Street
Portland, Maine

REVISION:
PER BSE FEB. 1 & 3 COMMENTS 02/04/16
PER BSE FEB. 22ND COMMENTS 02/24/16
03/18/16 BSE CONSTRUCTION MARKUPS
.

ISSUED:
FOR STRUCTURAL REVIEW 09/21/15
FOR STRUCTURAL REVIEW 11/12/15
FOR STRUCTURAL REVIEW 12/09/15
FOR BUILDING PERMIT 02/26/16

project architect: KAK
drawn by: JJD

PARKING GARAGE FDN. DETAILS

sheet number:
GS2.01

Friday, March 18, 2016 4:12:29 PM