Reviewed for Code Compliance
Inspections Division
Approved with Conditions

Date: 05/13/16

© Copyright 2016 Osc

7 PRECAST DOUBLE TEE BEARING AT CAST IN PLACE STAIR
1/2" = 1'-0"

6 PRECAST DOUBLE TEE BEARING AT CAST IN PLACE STAIR
1/2" = 1'-0"

5 PRECAST DOUBLE TEE BEARING AT RETAINING WALL
1/2" = 1'-0"

4 PRECAST DOUBLE TEE BEARING AT RETAINING WALL
1/2" = 1'-0"

3 PRECAST DOUBLE TEE BEARING AT RETAINING WALL
1/2" = 1'-0"

2 PRECAST DOUBLE TEE EDGE AT RETAINING WALL
1/2" = 1'-0"

1 PRECAST DOUBLE TEE EDGE AT RETAINING WALL
1/2" = 1'-0"

BECKER STRUCTURAL ENGINEERS
75 York Street, Portland, Maine 04101
207.879.1835 ■ beckerstructural.com

OPECHEE CONSTRUCTION CORPORATION
11 CORPORATE DRIVE ■ BELMONT ■ NH 03220
PHONE (603) 527-4009 ■ WWW.OPECHEE.COM

STATE OF MAINE
TODD M. NEAL
NO. 9406
LICENSED
PROFESSIONAL ENGINEER

Mixed Use Development

York & High Street
Portland, Maine

REVISION:
PER BSE FEB. 1 & 3 COMMENTS 02/04/16
WIDTH OF CONCRETE BEAM AT STAIRS 02/15/16
PER BSE FEB. 22ND COMMENTS 02/24/16
03/18/16 BSE CONSTRUCTION MARKUPS

ISSUED:
FOR STRUCTURAL REVIEW 11/12/15
FOR STRUCTURAL REVIEW 12/09/15
FOR BUILDING PERMIT 02/26/16
03/24/16 FOR CONSTRUCTION PER BSE

project architect: KAK
drawn by: JJD

PARKING GARAGE FDN. DETAILS

sheet number:
GS2.02

Thursday, March 24, 2016 1:28:10 PM