1st floor

plug 2 doors.
replace 1 door with
fire rated door

green walls are
not load bearing

Section

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 01/16/15