165
Cap to be added
at top of boards.
Solid stain or paint
to be applied to
entire fence.
View from Brackett Street, as built.
Actually this view is from Neal Street