Reviewed for Code Compliance
Inspections Division
Approved with Conditions

Date: 11/19/13

CONNECTION PLATES	
☐ ID	PART
4	b4
5	b5

SEE CLIP DETAILS S5.0

MEMBER TABLE		
MARK	PART	LENGTH
P-1	HSS 4x4x14ga	19'-11 1/16"
P-2	HSS 3x3x14ga	19'-11 1/16"
P-4	HSS 5x2x11ga	19'-10 1/2"
S-1	HSS 4x4x14ga	19'-2 3/8"
CB-1	1/2" CBL	266"
CB-2	1/2" CBL	254"
FB-1	L1.5x1.5x1/8"	3'-0"
FB-2	L2x2x3/16"	5'-0"
DH-1	DOUBLE 12C12	C.T.F.
DJ-1	12C12	C.T.F.
ST-1	8C14	C.T.F.
LF-1	6C14	C.T.F.
T-1	HSS 4x2x11ga	C.T.F.
TB-1	TRT. 2x6 BOARD	C.T.F.

NOTE:
ALL TOP FLANGES OF RIGID FRAME MUST BE BRACED WITH FLANGE BRACE OR SUPPORT PURLINS AT ALL NOTED PURLIN LOCATIONS

/ - DENOTES FLANGE BRACE LOCATION

STATE OF MAINE
DWAYNE R. MOENCH
13856
LICENSED
PROFESSIONAL ENGINEER
DRM
11-13-3

1 SIDEWALL FRAMING PLAN
AT GRID LINE N

2 SIDEWALL FRAMING PLAN
AT GRID LINE A

SCALE: 1/16" = 1'-0"

LEGACY BUILDING SOLUTIONS
www.legacybuildingsolutions.com
1.877.259.1828

NEW YARD LLC
120'-0" X 160'-6"
PORTLAND, ME

Legacy Building Solutions
19500 County Rd 142
South Haven, MN 55830
p. 320-259-7126

PATENT PENDING

SIDEWALL FRAMING PLAN

S3.1