DRAWN BY: JP / AN / SB / RV / MS



COMMUNICATIONS EQUIPMENT ROOM ENTRANCE SLEEVE DETAIL



TYPICAL THROUGH WALL SLEEVE DETAIL



TYPICAL CABLE ROUTING WITHIN A SPACE



TYPICAL SLEEVE MOUNTING DETAIL



TYPICAL DSS LAYOUT



MOUNTING HEIGHTS & CLEARANCES FOR PAY TELEPHONES



NOTES:
1. STRUCTURED CABLING SYSTEM OPPOSITE TO HINGE SIDE OF DOOR AND FOLLOW TYPICAL DIAGRAM TO RIGHT.

TYPICAL SLEEVE DETAIL INTO COMM ROOMS

1. SATELLITE DISHES SHALL FACE SOUTH. CONTRACTOR SHALL MAINTAIN A CLEAR LINE OF SIGHT TO SATELLITE.
2. ROOF PENETRATION TO THE CEILING BELOW. VERIFY CONDUIT SIZE REQUIREMENT WITH VENDOR SHOP DRAWINGS. SUGGESTED CONFIGURATION: ROOFTOP WP BOX MOUNTED UPRIGHT AND VERTICALLY ON A UNISTRUT FRAME WITH WEATHER HEAD(S) COMING OUT THE SIDE(S) – OR EQUIVALENT FOR EACH DISH.



VERIFY REQUIREMENTS WITH VENDOR SHOP DRAWINGS

CLEARANCE REQUIREMENTS FOR SATV

1

REFERENCED FLOOR PLAN BACKGROUND FILE DATE: 10/27/06
FILE NAME: Z:\ARCH\CY FORE\RIVER\CAMPUS_1515\CDs\MCM\CM\CMSC DETAILS.DWG
TIME: 24 AUG 2007 - 1:29 PM

Issued: 11/10/06

Issued For:
100 % CD's
For Construction

Revisions:
1 SI029 04/13/07

GB&A # 1515.1

Mercy Fore River Campus
Portland, Maine
Medical Communications

GB&A
GENE BURTON & ASSOCIATES
3281 East Guasti Road Suite 275
Ontario, California 91761
Phone: 909.605.1923
Fax: 909.605.1933
Web: www.gbainc.com

1893 General George Patton Drive
Franklin, Tennessee 37067
Phone: 615.376.3100
Fax: 615.376.3114
Web: www.gbainc.com

Sheet No.

Medical Communications
Misc Details

CM.02C.2