389 Congress St.rm 315
Portland, ME 04101
Phone: (207)874-8700
Fax: (207)874-8716

facsimile transmittal

To:	Ben Walter	**From:**	Mike Nugent
Fax:	774-4016	**Date:**	May 27, 2004
Phone		**Pages:**	1
Re:	Logan Place (076_A001)		

☐ **Urgent** ☐ **For Review** ☐ **Please Comment** ☑ **Please Reply** ☐ **Please Recycle**

I have started the review of the above project need the following info to continue:

1) Still need the certifications forms and a statement of special inspections
2) If we are classifying the structure as "5A" The exterior bearing walls must be 1 hour rated regardless of building location on the lot.
3) What are the UL Listing, Fire and STC Ratings of all of the assemblies on A0.1 that separate the units from each other and the corridors and stairways?
4) How are we handling the mixed-use components of this building?
5) In looking at the mechanical an electrical plans, there are significant penetrations, we should look at this closely to insure that we will be complying with Chapter 7.