389 Congress St.Rm 315
Portland, ME 04101
Phone: (207)874-8700
Fax: (207)874-8716

facsimile transmittal

To: Janet Hansen **From:** Mike Nugent

Fax: 772-1070 **Date:** June 17, 2003

Phone 772-3846 **Pages:** 1

Re: Glickman Library Project (114_d005)

☐ **Urgent** ☐ **For Review** ☐ **Please Comment** ☑ **Please Reply** ☐ **Please Recycle**

I am reviewing the above project and need the following:

1) A statement of Special Inspections for the structural infill area of the 6th floor system.
2) The 6th floor circulation is of concern, as the plan doesn't show how the "General Stacks" area will be organized with regard to exit access. The entire floor seems to be…a challenge, let's talk about it.
3) Does the elevator shaft extent to the basement floor and the underside of the roof sheathing?
4) What is the fire rating of the existing exit stairways?
5) What is the roof ceiling assembly rating?