Inspections Division
Date: 01/27/16

Ants: Antz, 66 Victor, Portland

1) Walls - exterior: (Not changing anything but siding & insulation)

, then insulation - interior (old insulation was sagging and useless !! ☹)

2) Bedroom windows are egress

3) Adding non-load bearing walls for a laundry room - 2x4"

4) Attic - unchanged and insulated

5) No load bearing walls affected

Notes: 1) Working without a contract with a handyman, a licensed electrician, and a licensed plumber. All are on time and materials basis, all parties in agreement.

2) Estimated renovation costs: $ 21,500

Antz - 66 Victor Road