Inspections Division
Date: 07/20/15

BASEMENT WALL DETAIL 1/4" = 1'0"

BOTTOM 24" OF DRYWALL REMOVED AND REPLACED WITH 1/2" MOISTURE RESISTANT DRYWALL