EXISTING ROOF FRAMING PLAN

1/8"=1'-0"

NOTES:

1. DAMAGED (E) SIDE WALL TRUSS FRAMING TO BE REPAIRED/REPLACED TO MATCH EXISTING. FIELD SKETCHES OF EXITING CONDITIONS AND REPAIRS ARE TO BE SUBMITTED FOR APPROVAL PRIOR TO FABRICATION.

2. ALL EXISTING WOOD PURLINS ARE TO BE INSPECTED FOR DETERIORATION PRIOR TO PLACEMENT OF NEW ROOF DECK. REPORT ANY AND ALL DETERIORATION TO ARCHITECT/ENGINEER OF RECORD.

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 06/17/14

Prepared For:
Thompson's Point Development Company Inc.

Consultant:
VEITASVEITAS engineers and
689 Granite Street, Suite 101
Braintree, Massachusetts 02184
Bethlehem, Pennsylvania 18015-4805

Architect:
ARCHETYPE architects
48 Union Wharf Portland, Maine 04101
(207) 772-6022 Fax (207) 772-4056

Project:
Depot
Thompson's Point Portland, ME

Revisions:

Scale: 1/8" = 1'-0"

Date: 02/11/14

Existing Roof Framing Plan

S101