Portland Maine | Yes. Google's good here.

Permitting and Inspections <buildinginspections@portlandm

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 05/02/17

Brick South Sprinkler System Drawing Revised 1/16/17

1 message

Ed Poulin <EPoulin@htfp.me> Tue, Jan 17, 2017 at 4:00 PM
To: Permitting and Inspections <buildinginspections@portlandmaine.gov>

Hello attached is the revised sprinkler drawings for the Brick South Building.

There is no longer protection along the buildings steel beams and will be protected by other means.

The check is in the mail today.

Thank you.

Ed Poulin

Design Manager

High Tech Fire Protection

Direct (207) 998-1330

Office (207) 998-2551

Fax (207) 998-4187

Epoulin@htfp.me

6 attachments

- **1 Thompson's Pt15 Invoice.pdf** 19K
- **Brick South FP-01 REVISED LAYOUT NO STEEL PROTECTION.pdf** 242K
- **Brick South FP-02 REVISED LAYOUT NO STEEL PROTECTION.pdf** 558K
- **Brick South Catering Area #2 Calc REVISED 1-16-17.pdf** 30K
- **Brick South Function Area #1 Calc REVISED 1-16-17.pdf** 28K
- **State Permit.pdf** 235K