EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106
Phone/Fax: (207) 517-6921 / (207) 517-6922
http://www.EMSL.com / portlandlab@emsl.com

EMSL Order ID: 6217(
Customer ID: ABAT
Customer PO: 17-06
Project ID:

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 05/15/17

Attn: Kris Rickett
Abatement Professionals Corporation
590 County Road
Suite #2
Westbrook, ME 04092

Proj: 17-063 / ECO MAINE

Phone: (207) 773-1276
Fax: (207) 772-1203
Collected: 3/29/2017
Received: 3/29/2017
Analyzed: 3/30/2017

Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

Client Sample ID: B1-Floor Tile ***Lab Sample ID:*** **621700463-0001**
Sample Description: SCALEHOUSE, FLOOR TILE.

TEST	Analyzed Date	Color	Non-Asbestos Fibrous	Non-Asbestos Non-Fibrous	Asbestos	Comment
PLM Grav. Reduction	3/30/2017	Tan/Various	0.0%	100%	None Detected	

Client Sample ID: B1-Mastic ***Lab Sample ID:*** **621700463-0001A**
Sample Description: SCALEHOUSE, FLOOR TILE.

TEST	Analyzed Date	Color	Non-Asbestos Fibrous	Non-Asbestos Non-Fibrous	Asbestos	Comment
PLM Grav. Reduction	3/30/2017	Brown	0.0%	100%	None Detected	

Client Sample ID: B2-Floor Tile ***Lab Sample ID:*** **621700463-0002**
Sample Description: SCALEHOUSE, FLOOR TILE.

TEST	Analyzed Date	Color	Non-Asbestos Fibrous	Non-Asbestos Non-Fibrous	Asbestos	Comment
PLM Grav. Reduction	3/30/2017	Tan/Various	0.0%	100%	None Detected	

Client Sample ID: B2-Mastic ***Lab Sample ID:*** **621700463-0002A**
Sample Description: SCALEHOUSE, FLOOR TILE.

TEST	Analyzed Date	Color	Non-Asbestos Fibrous	Non-Asbestos Non-Fibrous	Asbestos	Comment
PLM Grav. Reduction	3/30/2017	Brown	0.0%	100%	None Detected	

Client Sample ID: B3-Floor Tile ***Lab Sample ID:*** **621700463-0003**
Sample Description: SCALEHOUSE, FLOOR TILE.

TEST	Analyzed Date	Color	Non-Asbestos Fibrous	Non-Asbestos Non-Fibrous	Asbestos	Comment
PLM Grav. Reduction	3/30/2017	Tan/Various	0.0%	100%	None Detected	

Client Sample ID: B3-Mastic ***Lab Sample ID:*** **621700463-0003A**
Sample Description: SCALEHOUSE, FLOOR TILE.

TEST	Analyzed Date	Color	Non-Asbestos Fibrous	Non-Asbestos Non-Fibrous	Asbestos	Comment
PLM Grav. Reduction	3/30/2017				Insufficient Material	

Client Sample ID: B4 ***Lab Sample ID:*** **621700463-0004**
Sample Description: SCALEHOUSE, JOINT COMPOUND.

TEST	Analyzed Date	Color	Non-Asbestos Fibrous	Non-Asbestos Non-Fibrous	Asbestos	Comment
PLM	3/30/2017	White	0%	100%	None Detected	

EMSL Analytical, Inc.

161 John Roberts Road South Portland, ME 04106
Phone/Fax: (207) 517-6921 / (207) 517-6922
http://www.EMSL.com / portlandlab@emsl.com

EMSL Order ID: 6217(
Customer ID: ABAT
Customer PO: 17-06
Project ID:

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 05/15/17

Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116

Client Sample ID: B5 ***Lab Sample ID:*** **621700463-0005**

Sample Description: SCALEHOUSE, JOINT COMPOUND.

TEST	Analyzed Date	Color	Non-Asbestos Fibrous	Non-Asbestos Non-Fibrous	Asbestos	Comment
PLM	3/30/2017	White	0%	100%	None Detected	

Client Sample ID: B6 ***Lab Sample ID:*** **621700463-0006**

Sample Description: SCALEHOUSE, JOINT COMPOUND.

TEST	Analyzed Date	Color	Non-Asbestos Fibrous	Non-Asbestos Non-Fibrous	Asbestos	Comment
PLM	3/30/2017	White	0%	100%	None Detected	

PLM: Maine Analyst Certification # BA-0174, BA-0178

PLM EPA NOB: Maine Analyst Certification # BA-0174, BA-0178

Analyst(s):

Stephen Severn	PLM (2) PLM Grav. Reduction (4)
Zackary Carbee	PLM (1) PLM Grav. Reduction (1)

Reviewed and approved by:

CWalker

Christina Walker, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM alone is not consistently reliable in detecting asbestos in floor coverings and similar NOBs

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 03/30/201714:00:10