Inspections Division
Date: 10/08/15

S2 Custom Face Replacement (Linear Split) - Qty 2

Installation Guidelines

- Remove existing face from cabinet
- Install new face
- Verify electrical is in good working order
- Tech survey required to verify cut size prior to manufacturing

Film Application Diagram

priorityson

Revisions

File Location: Art\Dept\CorrectColors\Sprint

Date: 8-15-2015 | City/State: Portland ME | Drawing # C47118-S2

Designer: TD | PM: MP | Address: 1064 Brighton Ave | Site Name 7768-1108

9/16/2015