NORTH

NOTES

1. REFER TO EROSION CONTROL DETAILS ON C-103 AND EROSION CONTROL NOTES ON C-105.
2. INSTALL EROSION CONTROL BLANKET ON ALL DISTURBED SLOPES STEEPER THAN 3:1 BUT LESS THAN 1:1.
3. INSTALL RIPRAP EMBANKMENT ON SLOPES GREATER THAN OR EQUAL TO 1:1.

SCALE

0 10 20 40

SCALE in FEET
1"=20'

Site:

PROPOSED BUILDING
ACADEMY FOR
ACTIVE LEARNERS

134 WARREN AVENUE
PORTLAND, MAINE

Prepared for:

DELTA REALTY
380 WARREN AVENUE
PORTLAND, MAINE

STATE OF MAINE
STEPHEN J. BRADSTREET #5740
LICENSED PROFESSIONAL ENGINEER

CIVIL ENGINEER:

STEPHEN J. BRADSTREET, PE #5740
400 COMMERCIAL STREET, SUITE 404
PORTLAND, ME 04101
207-772-2891

RANSOM
Consulting Engineers and Scientists
400 Commercial Street, Suite 404
Portland, ME 04101
Tel. (207) 772-2891
Fax (207) 772-3248
www.ransomenv.com

UTILITY PLAN

No.	Revision/Issue	Date
C	RESPONSE TO CITY COMMENTS	02/19/16
B	RESPONSE TO CITY COMMENTS	01/25/16
A	PRELIMINARY REVIEW	12/01/15

Design by: MPM	Checked by: SJB
Drawn by: JAR	Approved by: SJB
Project: 151.06127	Date: OCTOBER 2015

Sheet No: C-101

Sheet 4 of 9