CITY OF PORTLAND FIRE PREVENTION BUREAU

DEGETVED AUG 16 2017

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

LARRY BUCHHOLZ 46 VESPER ST PORTLAND ME 04101 July 27, 2017

Location	CBL	Inspection Date
46 VESPER ST	003 1002001	6/30/2017
Inspector	Inspection Type	Status
Christopher Alves	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 8/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.2.1.9.2 FIRE DOOR DOES NOT CLOSE PROPERLY; Where door leaves are required to be self-closing or self-latching and are operated by power upon the approach of a person, or are provided with power-assisted manual operation, they shall be permitted in the means of egress where they meet the following criteria: (1) The door leaves can be opened manually in accordance with 7.2.1.9.1 (2) New door leaves remain in the closed position, unless actuated or opened manually (3) When actuated, new door leaves remain open for not more than 30 seconds (4) Door leaves held open for any period of time close-and the power-assist mechanism ceases to function- upon operation of approved smoke detectors installed in such a way as to detect smoke on either side of the door opening in accordance with the provisions of NFPA 72, National Fire Alarm Code (5) Door leaves required to be self-latching are either self-latching or become self-latching upon operation of approved smoke detectors per 7.2.1.9.2 (4) (6) New power-assisted swinging door assemblies comply with BHMA/ANSI A156.19, American National Standard for Power Assist and Lower Energy Power Operated needs self closing hinges on some doors and others need to be adjusted.	8/1/17 Dove
NFPA 101- 8.3.5 HOLE IN WALL NEEDS REPAIR; The provisions of 8.3.5 shall govern the materials and mathods of construction used to protect through-penetrations and membrane penetrations in fire walls, fire barrier walls, and fire resistance-rated horizontal assemblies. The provisions of 8.3.5 shall not apply to approved existing materials and methods of construction used to protect existing through-penetrations and existing membrane penetrations in fire walls, fire barrier walls, or fire resistance-rated horizontal assemblies, unless otherwise required by chapters 11 though 43. hole in plaster wall ,second floor back stairwell.	8/31/17
FINAL DATE OF COMPLETED VIOLATION(S)	9/1/17
FIRE PREVENTION BUREAU RE-INSPECTION OF COMPLETED VIOLATION(S)	_/_/_

The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

	ment, I understa <u>nd</u> that I am liable for penalties pursuant to the City of I-15 and 19-25, and 30-A M.R.S. § 4452 and may be subject to further legal
action. 8/14/17	La Buch
Date	Responsible Party
Date	Responsible Party
SEEN AND AGREED	CAPT. John
Date	Fire Prevention Bureau