CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

May 10, 2017

Responsible Party 1:				
Ricci John				
25 MARTIN RD				
PORTLAND, ME 04103				
Location	CDI	Imamastian Data		
Location	CBL	Inspection Date		
49 OBRION ST	003 I007001	5/2/2017		
		•		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 5/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.2.1.9.2 FIRE DOOR DOES NOT CLOSE PROPERLY; Where door leaves are required to be self-closing or self-latching and are operated by power upon the approach of a person, or are provided with power-assisted manual operation, they shall be permitted in the means of egress where they meet the following criteria: (1) The door leaves can be opened manually in accordance with 7.2.1.9.1 (2) New door leaves remain in the closed position, unless actuated or opened manually (3) When actuated, new door leaves remain open for not more than 30 seconds (4) Door leaves held open for any period of time close-and the power-assist mechanism ceases to function- upon operation of approved smoke detectors installed in such a way as to detect smoke on either side of the door opening in accordance with the provisions of NFPA 72, National Fire Alarm Code (5) Door leaves required to be self-latching are either self-latching or become self-latching upon operation of approved smoke detectors per 7.2.1.9.2 (4) (6) New power-assisted swinging door assemblies comply with BHMA/ANSI A156.19, American National Standard for Power Assist and Lower Energy Power Operated All self-closing hinges need to be adjuste to allow the fire doors to self-close and latch properly.	
NFPA 101- 7.1.3.2.1 60-MIN FIRE DOOR ASSEMBLIES REQ; The separation shall have a minimum 1-hour fire resistance rating where the exit connects three or fewer stories. 3rd floor rear	
NFPA 72- 10.2.1.2.2 SMOKE DETECTOR NEEDS REPAIR; System defects and malfunctions shall be corrected. rear hall	

Violation		Proposed Date of Completion
notification appliances used		IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
FINAL DATE OF COMPLI	ETED VIOLATION(S)	//
FIRE PREVENTION BUR	EAU RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	right to reject or modify any proposed plan of action, and magechnical capacity to complete the proposed plan. Please conta	=
understand that I must co	plations listed within the timeframes provided. If I require add contact the Fire Prevention Bureau <u>prior to the deadline</u> to req ceau's discretion to grant or deny.	1 .
v	t it is my responsibility to schedule a reinspection of my propo o so. My failure to schedule a reinspection shall be deemed a remedied.	•
	is agreement, I understand that I am liable for penalties purs unces $\S\S$ 1-15 and 10-25, and 30-A M.R.S. \S 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		

Fire Prevention Bureau

Date