CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

August 23, 2017

Responsible Party 1:				
43 O'Brion Street LLC				
21 Lower Falls Rd				
Falmouth, ME 04105				
Location	CBL	Inspection Date		
Location 43 OBRION ST	CBL 003 1009001	Inspection Date 7/25/2017		
		=		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 9/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.1.3.2.1 60-MIN FIRE DOOR ASSEMBLIES REQ; The separation shall have a minimum 1-hour fire resistance rating where the exit connects three or fewer stories. 3rd floor front apartment, 2nd floor rear apartment. Solid wood doors, possible just need certification only.	
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6. All 3 front apartments needed new CO detectors, also the 1st floor rear apartment. Owner stated he would replace units the next day. Additional smoke detectors were in the apartment.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 101- 31.3.6.2.3 DOORS MUST BE SELF-CLOSING; Doors that open onto exit access corridors shall be self-closing and self-latching. 3rd floor front apartment door needed to be adjusted. Had self closers but were not functioning correctly	-
NFPA 101- 31.3.6.3.1 REPAIR CORRIDOR WALLS; Unprotected openings, other than those from spaces complying with 31.3.6.3.2, shall be prohibited in exit access corridor walls and doors. Repair the hole in the rear stairwell wall, on the 2nd floor	
NFPA 1- 34.3.2.4 COMBUSTIBLES TOO CLOSE TO HEAT SOURCE; The clearance between stored materials and unit heaters, radiant space heaters, duct furnaces, and flues shall not be less than 3 ft in all directions or shall be in accordance with the clearances shown on the approval agency label. 1st floor front apartment, remove items from around the stove area. Plastic bags full of bottles, stacked next to burners	

Violation		Proposed Date of Completion
Code, on standards regarding ju	EQUIRE COVERS ; Refer to NFPA 70, National Electrical nction boxes requiring covers. niddle of the basment needed covers.	
	NSIDE BUILDING; No furnishings, decorations, or other eir access there to, egress therefrom, or visibility thereof.	
FINAL DATE OF COMPLETED	•	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
questions. VIOLATOR CERTIFICAT I agree to remedy the violatio understand that I must contact is entirely within the Bureau's	ns listed within the timeframes provided. If I require add t the Fire Prevention Bureau <u>prior to the deadline</u> to red	ditional time to comply, I quest an extension, which
· ·	My failure to schedule a reinspection shall be deemed a	•
	reement, I understand that I am liable for penalties purs \S 1-15 and 10-25, and 30-A M.R.S. \S 4452 and may be	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	