## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

November 8, 2017

Responsible Party 1:				
CICCOMANCINI SANTINO				
43 WALTON ST				
Portland, ME 04103				
Location	CBL	Inspection Date		
Location 47 MOODY ST	CBL 003 L016001	Inspection Date 10/12/2017		
		•		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 11/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation.  All apartment doors that are in the front and rear stairwells must be labled with the appropriate	·—/—/—
unit number.	
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  Hardwired photoelectric smoke alarms with battery backup need to be installed in the following	required. Your signature below indicates that temporary alarms have
locations: Unit 1 - Inside both bedrooms and 1 combination smoke/CO outside the bedrooms.  Unit 2 - Inside the bedroom. Unit 4 - Missing detector in the bedroom off the kitchen	andady boon motanean
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load.	//
Remove the storage rack and all materials from the 3rd floor rear stairwell landing. Egress stairwells cannot be used for storage.	
<b>NFPA 70 MISSING BREAKER IN PANEL</b> ; Refer to NFPA 70, National Electrical Code, for information on missing breakers in an electrical panel.	//
All 4 panels in the basement have missing breakers or gaps in the panels.	
NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; The areas described in Table 31.3.2.1.1 shall be protected as indicated: Boiler and fuel-fired heater rooms serving more than a single dwelling unit (minimum separation/protection is 1 hour or sprinklers) Install a domestic sprinkler head centrally located above the two furnaces.	//

Violation		Proposed Date of Completion
	ITE FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 lies for vertical shafts (including stairways, exits, and refuse ed for 1 hour.	//
60 minute rated, self-closing	fire doors are required in the following locations: 1) Basement 2 entry door in rear stairwell. 3) Both front and rear doors for Unit	
FINAL DATE OF COMPLET	TED VIOLATION(S)	//
FIRE PREVENTION BURE	AU RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	ight to reject or modify any proposed plan of action, and may chnical capacity to complete the proposed plan. Please contact CATION	-
understand that I must con	ations listed within the timeframes provided. If I require add ntact the Fire Prevention Bureau <u>prior to the deadline</u> to requ au's discretion to grant or deny.	
•	it is my responsibility to schedule a reinspection of my prope so. My failure to schedule a reinspection shall be deemed ar emedied.	•
	s agreement, I understand that I am liable for penalties pursunces §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	