## Portland, Maine



## Yes. Life's good here.

Fire Department
Fire Prevention & Education

Jerome F. LaMoria Chief of Department

HOOVER MICHALE LIONEL & 86 BECKETT ST PORTLAND, ME 04101

CBL: 003 L005001 Located at 86 BECKETT ST

Mail

Dear Mr. Hoover,

The Portland Fire Department recently conducted an inspection of your property referenced above to ensure compliance with state and local fire safety regulations. See attached violation notice. While conducting this inspection, we identified life safety code violations as more particularly described in the attached violation notice. See attached.

You have until thirty-two (32) days from the date of this notice to correct the violations outlined in the attached notice. If the corrections cannot be accomplished by this date, please contact the Fire Prevention Office at (207) 874-8400 upon receipt of this notice to discuss the matter and the process to submit a Plan of Action for addressing these safety issues.

Please note that one (1) follow-up inspection will be done to ensure that your property is brought into compliance. Should any additional inspections be required you will be charged \$150.00 for each reinspection. See Portland City Code, Chapter 10, Fire Prevention and Protection, § 10-25.2 available on-line at www.portlandmaine.gov.

If all of the violations cited above have not been corrected by the above referenced compliance date, or the date contained within a Plan of Action approved by the Portland Fire Department, this matter will be referred to the City of Portland Corporation Counsel for legal action and possible civil penalties as provided for in Portland City Code, Chapter 10, Fire Prevention and Protection, § 10-25 and in Title 30-A M.R.S.A.

This is an appealable decision pursuant to Portland City Code, Chapter 10, Fire Prevention and Protection, § 10-23. As such, you have ten (10) days from the date of this notice to appeal to the Board of Appeals. See Portland City Code, Ch. 10 § 10-23.

Thank you in advance for your prompt attention to this matter. Please contact us at fireinspector@portlandmaine.gov or (207) 874-8400 with any questions.

Sincerely,

David Petruccelli @ 207-874-8400

Fire/Plan Review

## CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

## Inspection Violations

Owner/Manager HOOVER MICHALE LIONEL &				Inspector David Petruccelli		Inspection Date 3/31/2015
Location 86 BECKETT ST		CBL 003 L005001		Status Failed		Inspection Type Complaint-FP Routine Inspection
1) 69.25						
Violation:	PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 RESIDENTIAL UNITS SHALL BE DESIGNATED USING NUMERALS.					
	4.6.2 THE FIRST NUMERAL OF EACH RESIDENTIAL UNIT SHALL BE THE FLOOR DESIGNATION					
Notes:	Apartment doors require marking front and rear doors					
2) 71.05						
Violation:	NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6.					
Notes:		•			·	·
3) 71.25						
Violation:	NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.					
Notes:		Þ				-
4) 9.002						
Violation:	NFPA 80- ANNEX D.4 1-HOUR FIRE DOORS ASSEMBLIES REQ; Listings are provided for floor fire door assemblies that are installed in fire-rated floor-ceiling or roof-ceiling assemblies that have ben tested in accordance with the methods described in NFPA 288. The listing indicates the fire-rated assembly and the hourly rating (3 hours, 2 hours, 1.5 hours, 1 hour, .75 hours) for which the door can be permitted to be used so that access to the space above the ceiling or to the floor above can be provided without adversely affecting the fire resistance rating of the entire assembly. The listing provides limitations on the maximum size of an individual door opening and the total area of all door openings permitted for each 100 ft. squared of floor or ceiling.					
Notes:	1st and 3rd floor units					
5) 89.05			_			
Violation:	NFPA 1- EXCESSIVE/DISORDERLY STORAGE; REFERENCE NFPA 1 FOR EXCESSIVE FUEL-LOAD.					
		- EXCESSIVE	/DISORDE	RLY STORA	GE; REFERE	ENCE NFPA 1 FOR EXCESSIVE FUEL-

Comments: