

**From:** Bruce Hyman  
**To:** Jean Fraser  
**CC:** Barbara Barhydt; David Margolis-Pineo; Errico Thomas; Jeremiah Bartlett  
**Date:** 4/4/2014 11:05 AM  
**Subject:** Re: Crosswalk for Munjoy Heights (Walnut) - DPS Staff Recommendation  
**Attachments:** MunjoyHgts\_WalnutStCrosswalkDPSSStaffRecommend\_Apr04-14.pdf

Good morning, Jean,

The consensus among Tom E, Jeremiah and me is for Option #1 with a slight re-alignment of the crosswalk and location of the curb ramp on the west side of Walnut St.

The crosswalk should be oriented/located such that it has at least 4'x4' of landing area within the crosswalk at the base of the ramp at the Sheridan St corner. The crosswalk must also extend the full width of the bottom ramp where it meets the street.

I've attached a quick sketch showing the recommended orientation and location of curb ramps and the crosswalk.

Please have the applicant contact me directly if there are any additional questions.

Best regards,

Bruce

**Bruce Hyman**  
Bicycle & Pedestrian Program Coordinator

City of Portland, Maine  
Dept. of Public Services  
bhyman@portlandmaine.gov  
207-874-8833

>>> Jean Fraser 3/28/2014 3:41 PM >>>  
Tom and Bruce

Attached are the plans that were submitted for these projects (as submitted by applicant to address the condition) and I have not seen any comments from DPS back to the applicants. I think these were discussed internally a few weeks ago and it would be helpful if formal comments could be agreed and sent to the applicant (if they have not already been sent - in which case pl forward to me)

Re **118 Congress**, they have submitted a final site plan with the crosswalk shown in attach 2 to this e-mail (for our review and approval in the next week- it has been circulated to DPS as part of a set requiring a sign off) and are working hard to get the plans finalized because they want to get a building permit.

Re **Munjoy Heights**, the location of the crosswalk and the way it ties in with the apron and sidewalk and woonerf materials needs to be agreed soon so that a report to the City Council re substitute apron materials can be prepared.

Maybe its just that I am out of the loop, but in both cases this relates to other things that I am trying to coordinate, hence this e-mail to follow up.

Many thanks  
Jean

874 8728