## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

August 1, 2017

Responsible Party 1:				
Duffey Aaron				
24 Catherine St				
Portland, ME 04102				
Location	CBL	Inspection Date		
<b>Location</b> 62 WASHINGTON AVE	<b>CBL</b> 013 C014001	Inspection Date 7/12/2017		
		<del>-</del>		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 8/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101-31.3.2.1 AND 31.3.2.1.1 PROTECTION OF HAZARDOUS AREAS NOT PROVIDED; Any hazardous area shall be protected in accordance with Section 8.7. The areas described in Table 31.3.2.1.1 shall be protected as indicated.  Need walls sealed between basement apt. and boiler room	//
<b>NFPA 101- 7.5.1.1 EXIT OBSTRUCTED</b> ; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. Storage in 1st floor hallway	IMMEDIATELY remove all obstructions from the exits. Your signature below indicates that all obstructions have been removed and will not be replaced.
<b>NFPA 101- 7.5.1.1.1 SECOND EXIT REQUIRED</b> ; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to no less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. Basement Apartment needs a second exit	//
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  Need a smoke detector in basement apt. bedroom	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.

Violation		Proposed Date of Completion
NFPA 1 EXCESSIVE/DISORDI	ERLY STORAGE; Reference NFPA 1 for excessive fuel-load.	/ /
Storage on the 1st floor		//
NFPA 70 MISSING BOX COVE for missing box covers.	ERS; Refer to NFPA 70, National Electrical Code, on standards	//
Missing switch, outlet, and junc		
FINAL DATE OF COMPLETE	D VIOLATION(S)	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
_	t to reject or modify any proposed plan of action, and may rical capacity to complete the proposed plan. Please contact	_
understand that I must conta	ons listed within the timeframes provided. If I require addited to the Fire Prevention Bureau prior to the deadline to requies a discretion to grant or deny.	
v	s my responsibility to schedule a reinspection of my proper My failure to schedule a reinspection shall be deemed an edied.	-
	greement, I understand that I am liable for penalties pursuces $\S\S$ 1-15 and 10-25, and 30-A M.R.S. $\S$ 4452 and may be s	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	