



ALL HANDRAILS TO MEET IBC SECTION 1012.

ALL UNITS ARE TO BE SEPARATED FROM EACH OTHER WITH 30-MINUTE FIRE-SEPARATIONS (WALLS AND FLOOR/CEILINGS). WALLS SHALL HAVE 1/2" GYP BOARD ON EACH SIDE OF THE WALL (U.L. #U319). FLOOR/CEILINGS SHALL HAVE 1/2 GYP BOARD ATTACHED TO THE UNDERSIDE OF THE FLOOR JOISTS. ALL ASSEMBLIES SHALL BE FIRE-CAULKED AS REQUIRED. ALL BATHROOMS TO HAVE MOISTURE-RESISTANT GYP BOARD.
SEE STRUCTURAL DRAWINGS FOR ADDITIONAL INFORMATION.
FLOOR/CEILING ASSEMBLIES BETWEEN RETAIL AREAS AND APARTMENT UNITS (IN OFFICE AREA IØ4, VESTIBULE IØ4A, AND BATH IØ5, THAT CURRENTLY HAVE THE CEILINGS REMOVED) ARE TO BE 1-HOUR RATED. SEE DETAIL 3, SHEET AI.2 FOR TOP OF INTERIOR WALL DETAIL. THE RATED FLOOR/CEILING ASSEMBLY SHALL BSIMILAR TO UL. DESIGN #L513 AND APPROVED BY THE AUTHORITY HAVING JURISDICTION. CEILINGS IN THE RETAIL AREAS ARE EXISTING AND SHALL REMAIN ON THE FIRST FLOOR RETAIL SPACE, MOST OF THE FINISHES ARE STILL IN PLACE. HOWEVER, SOME PORTIONS OF THE EXISTING WALLS NEED TO BE REPLACED OR FIXED. PLEASE REFER TO THE WALL TYPES ON THE PLAN FOR HOW THE WALLS SHOULD BE REPAIRED AND/OR UPDATED. (NOTE: IT IS THE UPPER FLOORS WHERE ALL FINISHES HAVE BEEN REMOVED).

BATH 105 AND 107 ARE FOR EMPLOYEE USE ONLY AND NOT INTENDED FOR PUBLIC USE.

EXISTING FLOOR / CEILING SYSTEM EXISTING FLOOR / CEILING STRUCTURE FILL EXISTING STUD CAVITY WIR-21 (MIN.) SOUND ATTENUATION. EXTERIOR WALL (EXTERIOR SIDING W/2 x 4 WD. STUD BACK-UP) FIRE CAULKING SEALANT (TYP.) 5/8" TYPE "X" GYPSUM BOARD EXISTING EXTERIOR SIDING WALL SYSTEM EXISTING DBL TOP PLATE ——— EXISTING 2x4 WD BASE EXISTING WD STUDS BASE BY OWNER BASE PLAN HEAD





65 NEWBURY STREET PORTLAND, ME 04101 207.761.9000 fax: 207.761.2010 info@portcityarch.com

229 Congress St Apartments

GENERAL

NOTES

Portland,

8-15-13 Maine REVISIONS

Project Number Date Issued Aug 15, 2013 AS NOTED

FLOOR PLANS

Checked By

 $\sqrt{}$