CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

October 25, 2017

Responsible Party 1:					
Kelly Mary					
PO Box 617					
Portland, ME 04104					
Location	CBL	Inspection Date			
Location 48 NORTH ST	CBL 013 K016001	Inspection Date 9/22/2017			
		-			

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 11/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.5.1.1 EXIT OBSTRUCTED ; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. storage in stairways	IMMEDIATELY remove all obstructions from the exits. Your signature below indicates that all obstructions have been removed and will not be replaced.
NFPA 101- 7.2.1.8.1 FIRE DOORS MUST BE SELF- OR AUTO-CLOSING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3. Fire Doors on 3rd floor need to self close completely	//
NPFA 101- 7.2.2.1.1 STAIRS REQUIRE REPAIR; Stairs shall meet the following criteria: (1) New stairs shall be in accordance with Table 7.2.2.2.1.1(a) (2) Existing stairs shall be permitted to remain in use, provided that they meet the requirements for existing stairs shown in Table 7.2.2.2.1.1(b) (3) Approved existing stairs shall be permitted to be rebuilt in accordance with the following: (a) dimensional criteria of table 7.2.2.2.1.1(b) and other stair requirements of 7.2.2 (4) The requirements for new and existing stairs shall not apply to stairs located in industrial equipment access areas where otherwise provided in 40.2.5.2. Front Entry	//

Violation		Proposed Date of Completion
through out with an existing, compl be installed in accordance with 9.6.	ARMS REQUIRED; In buildings other than those equipped ete automatic smoke detection system, smoke alarms shall 2.10, as modified by 31.3.4.5.2, outside every sleeping e bedrooms and on all levels of the dwelling unit, including	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 1 EXCESSIVE/DISORDERL Basement Excessive storage.	Y STORAGE; Reference NFPA 1 for excessive fuel-load.	//
FINAL DATE OF COMPLETED VI	OLATION(S)	//
FIRE PREVENTION BUREAU RE	-INSPECTION OF COMPLETED VIOLATION(S)	//
_	reject or modify any proposed plan of action, and may capacity to complete the proposed plan. Please contact N	-
•	listed within the timeframes provided. If I require add he Fire Prevention Bureau <u>prior to the deadline</u> to requ iscretion to grant or deny.	1 .
	y responsibility to schedule a reinspection of my prope ly failure to schedule a reinspection shall be deemed an ed.	
0 0 1 0	ement, I understand that I am liable for penalties pursu § 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	2 0
Date	Responsible Party	
Date SEEN AND AGREED	Responsible Party	
Date	Fire Prevention Bureau	