## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

September 15, 2017

Responsible Party 1:				
YUN HATT				
3 HOWARD ST #3				
PORTLAND, ME 04101				
-				
Location	CBL	Inspection Date		
Location 22 HOWARD ST	CBL 014 F007001	Inspection Date 8/18/2017		
		_		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 9/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.1.3.2.1 60-MIN FIRE DOOR ASSEMBLIES REQ; The separation shall have a minimum 1-hour fire resistance rating where the exit connects three or fewer stories. Rear stairway. Furnace in closet on second floor, needs fire door.	
NFPA 101- 7.2.1.8.1 DOORS SHALL BE SELF-CLOSING & SELF-LATCHING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise specified by 7.2.1.8.3.  All	
NFPA 70 JUNCTION BOXES REQUIRE COVERS; Refer to NFPA 70, National Electrical Code, on standards regarding junction boxes requiring covers.	
NFPA 70 PLUG OPENINGS IN FUSE PANEL; Refer to NFPA 70, National Electrical Code, regarding plugging open fuses in panels.  Panel in basement needs open breakers covered	
NFPA 101- 31.3.6.3.1 REPAIR CORRIDOR WALLS; Unprotected openings, other than those from spaces complying with 31.3.6.3.2, shall be prohibited in exit access corridor walls and doors.  Rear hallway, 3rd floor. Furnace has louver into hallway.	
NFPA 101- 31.2.2.1.2 1-HOUR FIRE RATED EXIT ENCLOSURES AND DOORS; In buildings using Option 4, exit enclosures shall have a minimum 1-hour fire resistance rating, and doors shall have a minimum 1-hour fire protection rating.  2nd floor front stairs, two doors into one apartment, one is not fire rated. Can be replaced with fire rated or removed and drywalled over.	

Violation		Proposed Date of Completion
31.3.2.1.1 shall be protected than a single dwelling unit (m	R PROTECTION REQUIRED; The areas described in Table as indicated: Boiler and fuel-fired heater rooms serving more inimum separation/protection is 1 hour or sprinklers) needs a sprinkler instaled in closet.	
FINAL DATE OF COMPLET	ED VIOLATION(S)	//
FIRE PREVENTION BUREA	U RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	tht to reject or modify any proposed plan of action, and may nnical capacity to complete the proposed plan. Please contact ATION	-
understand that I must con	tions listed within the timeframes provided. If I require add tact the Fire Prevention Bureau <u>prior to the deadline</u> to req u's discretion to grant or deny.	
· ·	t is my responsibility to schedule a reinspection of my prope to. My failure to schedule a reinspection shall be deemed a medied.	-
	agreement, I understand that I am liable for penalties pursices §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	