CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

January 9, 2017

Responsible Party 1:	Responsible Party 2:	
TOMLINSON JTS JESSICA J	Wolyniec Henry	
24 TAYLOR ST	24 Taylor Street	
PORTLAND, ME 04102	Portland, ME 04102	
Location	CBL	Inspection Date
50 TURNER ST	014 J001001	1/5/2017
Inspector	Inspection Type	Status
Jonathan Hendricks	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must complete the proposed date of completion column by proposing a reasonable timeframe to remedy each violation. This form must be received by the Fire Prevention Bureau no later than 1/30/2017. The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION BY THE DATE PROVIDED, OR TO CORRECT ANY VIOLATION WITHIN THE APPLICABLE TIME FRAME, MAY RESULT IN LEGAL ACTION AGAINST YOU, THE IMPOSITION OF CIVIL PENALTIES, AND THE PURSUIT OF OTHER LEGAL REMEDIES.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. FRONT & REAR STAIRS- ALL apt. doors need labels	//
NFPA 101- 31.3.7 FLOOR/ CEILINGS ASSEMBLY NOT SMOKE-TIGHT; In buildings other than those meeting the requirements of 31.3.7.1, 31.3.7.2, 31.3.7.3, 31.3.7.4, or 31.3.7.5, in addition to the following criteria to be met. REAR STAIRS- Electrical wires cut into plaster above apt door.	//
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements. BASEMENT- Missing Smoke/CO dectector	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 70- 590.6 EXTENSION CORDS; Ground-fault protection for personnel for all temporary wiring installations shall be provided to comply with 590.6(A) and (B). This section shall apply only to temporary wiring installations used to supply temporary power to equipment used by personnel during construction, remodeling, maintenance, repair, or demolition of buildings, structures, equipment, or similar activities. BASEMENT STAIRS- Extension cord used as perminant wiring needs to be removed.	//

Violation		Proposed Date of Completion
FIRED GRILL, CHARCOAL GRILL, OF HEATING, OROTHER PURPOSE, SH	CHI OR GRILL ON BALCONY; NO HIBACHI, GAS- R OTHER SIMILAR DEVICES USED FOR COOKING, ALL BE USED OR KINDLED ON ANY BALCONY OR OR WITHIN 10 FTOF ANY STRUCTURE	//
		//
VIOLATOR CERTIFICATION		
understand that I must contact the Frentirely within the Bureau's discretion I further understand that it is my results.	ed within the timeframes provided. If I require additive Prevention Bureau prior to the deadline to request on to grant or deny. Sponsibility to schedule a reinspection of my proper additive to schedule a reinspection shall be deemed an	est an extension, which is ety once the violations
1 2	nt, I understand that I am liable for penalties pursua 5 and 10-25, and 30-A M.R.S. § 4452 and may be	•
Date	Responsible Party	
Date	Responsible Party	<u></u>
SEEN AND AGREED		

Fire Prevention Bureau

Date