


13. INT - 1ST FLOOR APT 1 - BATHROOM Floor rotted under toilet	108.20
14. INT - 1ST FLOOR APT 1 - BATHROOM Broken handle tub fixture	111.40
15. INT - 2ND FLOOR APT 2 - ENTIRE Loose ceiling fixtures broken light switch	113.50
16. INT - 2ND FLOOR APT 2 - BATHROOM Floor rotted under toilet	108.20
17. INT - 2ND FLOOR APT 2 - ENTIRE Peeling paint	108.10
18. INT - 2ND FLOOR APT 2 - ENTIRE Missing door handles on front bedroom, back hall and middle bedroom	108.20
19. INT - 2ND FLOOR APT 2 - PANTRY 3" flue pipe in chimney covered with duct tape	108.50
20. INT - 3RD FLOOR APT 3 - ENTIRE No cover on junction box loose fixtures	113.50
21. INT - APTS 1, 2, 3 & HALLS No hard wired batter back up smoke detectors, they are required in each unit and entry hall	113.50

Please be advised that the Portland City Council has amended the Building regulations to include a \$75.00 reinspection fee. This violation will automatically cause a reinspection at no charge. If there are any subsequent inspections, however, the \$75.00 fee will be assessed for each inspection. A copy of the amendment has been attached for your convenience.

Sincerely



Tom Reinsborough
Code Enforcement Officer

/sap

cc/Central File