CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

August 18, 2017

Responsible Party 1:				
DiDonato Frank				
87 SKYLARK RD				
PORTLAND, ME 04103				
Location	CBL	Inspection Date		
Location 53 KELLOGG ST	CBL 017 A007001	Inspection Date 8/2/2017		
		=		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 9/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.1.3.2.1 60-MIN FIRE DOOR ASSEMBLIES REQ; The separation shall have a minimum 1-hour fire resistance rating where the exit connects three or fewer stories. Basement door is required to be fire rated and self-closing	
NPFA 101- 590.6 DISCONTINUE USE OF EXTENSION CORDS; Ground-fault protection for personnel for all temporary wiring installations shall be provided to comply with 590.6(A) and (B). This section shall apply only to temporary wiring installations used to supply temporary power to equipment used by personnel during construction, remodeling, maintenance, repair, or demolition of buildings, structures, equipment, or similar activities. Two extension cords in the basement.	
CITY ORDINANCE HARDWIRED SMOKE DETECTORS REQUIRED; New smoke alarms shall be powered in accordance with NFPA 72. Where available options include: Hardwired with battery back up A non-rechargeable, non-replaceable primary battery that is capable of operating the device for at leat 10 years Existing smoke alarms shall be hardwired and replaced every 10 years with smoke alarms complying with the above notes. All new smoke alarms shall be photoelectric. 2nd and 3rd flloor apartments. Both inside bedrooms and immediately outside room.	
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6. In every unit and basement	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.

Violation		Proposed Date of Completion
buildings or areas between which	RIER REQUIRES MAINTENANCE; Fire barriers separating the there are horizontal exits shall have a minimum 2-hour fire ise provided in 7.2.4.4.1, and shall provide a separation that is ided level.	//
_	ot vent into halls. Walls need to be maintain a 1 hour rating.	
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	to reject or modify any proposed plan of action, and may cal capacity to complete the proposed plan. Please contaction	-
understand that I must contact is entirely within the Bureau'. I further understand that it is	my responsibility to schedule a reinspection of my prope My failure to schedule a reinspection shall be deemed ar	nest an extension, which rty once the violations
	reement, I understand that I am liable for penalties pursus $\S\S$ 1-15 and 10-25, and 30-A M.R.S. \S 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	