CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

April 21, 2017

Responsible Party 1:				
Body David				
46 WATERVILLE ST				
PORTLAND, ME 04101				
Location	CBL	Inspection Date		
46 WATERVILLE ST	017 E012001	4/5/2017		
Inspector	Inspection Type	Status		
Steven Hall	FP Routine Inspection	Failed		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 5/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements. Need a smoke detector 1st floor apt.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 101- 7.2.1.15.8 FIRE DOOR ASSEMBLY REQ REPAIR; Door openings not in proper operating condition shall be repaired or replaced without delay. 1st and 2nd floor laundry room	//
NFPA 101- 31.3.7 FLOOR/ CEILINGS ASSEMBLY NOT SMOKE-TIGHT; In buildings other than those meeting the requirements of 31.3.7.1, 31.3.7.2, 31.3.7.3, 31.3.7.4, or 31.3.7.5, in addition to the following criteria to be met. 1st and 2nd floor laundry sheet rock needs repair	//
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6. All apartments in common area	//

Violation		Proposed Date of Completion
through out with an existing, complebe installed in accordance with 9.6.2	RMS REQUIRED; In buildings other than those equipped to automatic smoke detection system, smoke alarms shall .10, as modified by 31.3.4.5.2, outside every sleeping bedrooms and on all levels of the dwelling unit, including	//
FINAL DATE OF COMPLETED VIC	DLATION(S)	//
FIRE PREVENTION BUREAU RE-I	NSPECTION OF COMPLETED VIOLATION(S)	//
	eject or modify any proposed plan of action, and may capacity to complete the proposed plan. Please contact	-
•	isted within the timeframes provided. If I require addic Fire Prevention Bureau <u>prior to the deadline</u> to requ Ecretion to grant or deny.	- ·
·	responsibility to schedule a reinspection of my proper failure to schedule a reinspection shall be deemed an d.	•
	nent, I understand that I am liable for penalties pursul-1-15 and 10-25, and 30-A M.R.S. § 4452 and may be s	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	