

Client: Quality Assurance Laboratories
Project: Marriott Hotel Portland, ME
Date: September 25, 2008
Subject: Inspection and Testing of Field Welds

Report: 001

A site visit was made on this date to inspect and conduct ultrasonic testing of moment connection welds. Locations inspected and tested are documented on the enclosed ultrasonic test report.

All welds were found acceptable with the following exceptions or comments:

- A10 bottom flange west was rejected. This is to be repaired
- A14 was visually unacceptable. This was corrected.
- A12 had missing shop weld. This was corrected.
- D10 has a 1" crack in the shop weld. This was marked for repair.

All discrepancies were marked adjacent to the weld.

Inspector; Neal J White

