

Field Report

sv_2007/02/09

Project: Pearl Place
Project #: 1605
Date/Time: 2/7/09-2:00 PM to 2:45 PM
Observers Michael Cyr

Building 2:

The subcontractor was removing forms from the concrete wall along Pearl Street.

I observed the wall reinforcement for the interior concrete foundation wall which runs parallel to Oxford Street. The general contractor had snapped a chalk line on the foundation to identify the limits of the wall. Some of the #7 bars were 3" from the face of the wall. After reviewing the calculations, the as-built condition is considered acceptable.

Building 1:

The concrete foundation work appears complete. The waterproofing subcontractor was on site.

CC: Mike Myatt, Ronald Norton, Pandika Pleqi, Rick Nanartowich, Clint Gendreau, Dave Schoenherr, Suzanne Hunt Job File—1605