## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

April 13, 2017

Responsible Party 1: Repsonsible Party2:		Repsonsible Party2:
Fitzpatrick Daniel	Fitzpatrick Daniel	
P.O. Box 143	41 Oak Dr	
Westbrook, ME 04098	Gray, ME 04039	
Location	CBL	Inspection Date
Location 51 CHESTNUT ST	CBL 026 F010001	Inspection Date 3/30/2017

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 4/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. apt. doors	//
NFPA 101- 7.2.1.15.8 FIRE DOOR ASSEMBLY REQ REPAIR; Door openings not in proper operating condition shall be repaired or replaced without delay. self closers not working	//
<b>NFPA 101- 7.5.1.1.1 SECOND EXIT REQUIRED</b> ; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to no less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. 2nd floor units	//
NFPA 101- 7.2.2.5.1.1 EXIT STAIRS NOT SEPARATED.; All inside stairs serving as an exit or exit component shall be enclosed in accordance with 7.1.3.2. 2nd floor	//
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  2nd floor apt. bedroom, replace detector	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.

Violation		Proposed Date of Completion
	<b>FIRE DOOR REQUIRED</b> ; Refer to NFPA 101- Table 8.3.4.2 for vertical shafts (including stairways, exits, and refuse or 1 hour.	//
FINAL DATE OF COMPLETED	O VIOLATION(S)	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	to reject or modify any proposed plan of action, and may ical capacity to complete the proposed plan. Please contaction	
•	ons listed within the timeframes provided. If I require add to the Fire Prevention Bureau <u>prior to the deadline</u> to requ to discretion to grant or deny.	
v	s my responsibility to schedule a reinspection of my prope My failure to schedule a reinspection shall be deemed an edied.	•
	greement, I understand that I am liable for penalties pursus $\S \$ 1-15 and 10-25, and 30-A M.R.S. $\S \$ 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	